



## 5 Star Extinguisher Services

6/159 Chifley Street Wetherill Park NSW 2164

ABN: 55 209 172 495

P.O. Box 345 Toongabbie NSW 2146

**Telephone:** (02) 9609 7420 **Mobile:** 0413 283 150 **Facsimile:** (02) 9609 6303

# INSPECTION PROCEDURES FIRE HOSE REELS

**Reference:** AS 2444  
AS/NZS 1851-2

### Inspection Checks Include:

**1. SIX MONTHLY INSPECTION:**

- ✓ *Instructions for operation are clearly legible.*
- ✓ *That there is no leakage of water exceeding 5mL in a 3 minute period from the valve gland, spindle gland, or discharge nozzle with the stop valve turned fully open, the nozzle closed, and the hose partially run to at least 5 m..*
- ✓ *The hose runs smoothly through the guide.*
- ✓ *There are no signs of corrosion or damage, which may adversely affect the operation of the reel.*

**2. TWELVE MONTHLY INSPECTION:**

- ✓ *As per SIX MONTHLY INSPECTION however, flow test of not less than 0.33L/s with the nozzle in the jet mode.*

**3. LOCATION SIGNS AND PATHWAYS CLEARLY VISIBLE**